

TAMAR SECURITY

DOMESTIC AND COMMERCIAL FIRE AND SECURITY SOLUTIONS

Ulysses Park, Exeter, Devon EX2 7PH

T: 01392 368830

E: admin@tamarsecurity.co.uk

www.tamarsecurity.co.uk

CUSTOMER JOB NO. 244905 - 47245 - Justin Chaplin Fire Alarm - Maintenance

Site Details

Name Stowford Community Centre
Address Chambers Close
Sidmouth Devon EX10 9YL
Contact Bob Weeks
Telephone 01395 576803
Mobile 07973252834
Email

Customer Details

Name Stowford Community Centre
Address Chambers Close
Sidmouth Devon EX10 9YL
Contact
Telephone 01297 33554
Mobile
Email stowfordcommunity@btconnect.com

Work Requested

Fire Alarm 6 Monthly

Schedule

Date Schedule	Date Performed	Scheduled Start	Scheduled Finish	Actual Start	Actual Finish	Total
22/07/2025	22/07/2025	12:30	13:45	12:15	13:30	1.25 hrs

Work to be Performed

Description	Required

Work Completed

Routine service of fire alarm system.
Tested 50%
Tested children centre corridor.
Tested mcps
Tested kitchen.
Tested store room.
Tested mcps.
Tested batteries
Tested bells

Recommendations.

- 1) main fused spur not fire rated to bs 5839 2017
- 2) Zone chart not very clear.

Tamar Security Ltd is registered in England
and Wales, Registration No. 05455843
VAT Registration No. 857 7423 87
Director: Martin Shearer



CERTIFICATE NO. NAC/G/1835

TAMAR SECURITY

DOMESTIC AND COMMERCIAL FIRE AND SECURITY SOLUTIONS

Ulysses Park, Exeter, Devon EX2 7PH

T: 01392 368830

E: admin@tamarsecurity.co.uk

www.tamarsecurity.co.uk

CUSTOMER JOB NO. 244905 - 47245 - Justin Chaplin Fire Alarm - Maintenance

Log book completed

Asset Register - 2: System: Fire Alarm - Commercial - BS5839:2025

Asset ID	System Description	Location	Make	Model	Grade/Level	Date Tested	Pass / Fail
6141	Fire Alarm: BS5839-Part 1 (Commercial)	##Fire panel is a Twin Surveyor XLKHS in entrance lobby.## Apollo series 65 protocol.Customer test EL's themselves*** Fire - Annual service requires poles for high level smokes .				22/07/2025	Pass
Test Readings	Is the system log book available: Yes				Any false alarms noted in Log Book. Does the number exceed 1 per 25 detectors: 0		
	What category does system look like, if no spec on site: L2?				Remote signalling, if applicable check and confirm with ARC time signal received Fire@ Fault@: Not applicable		
	Check all Fire Alarm functions of the FAP: Yes				Check all LED illumination indicators and displays on FAP: Yes		
	Check all fault indicators by simulating faults: Yes				Is zone diagram in place and correct: Yes		
	Confirm visually all cables are securely clipped with fire resisting clips as appropriate: Yes				Battery current in quiescent in MA: 100		
	Battery current in alarm in MA: 1100				Calculate battery size $c=[(i1 \times T1)+i2] \times 1.25$: 4.5		
	Confirm all MCPs not obstructed: Yes				Operate and MCP or automatic detector on each conventional FAP zone: All zones tested		
	Functionally test Automatic Detectors i.e 25%,50%,75% or 100% against schedule or colour code and note any not tested: 50%				Carry out sounder test and confirm all sounders working: Bells tested		
	Confirm clear space of 500mm is maintained below each automatic detector: Yes				Confirm storage does not encroach within 300mm of a ceiling: Yes		
	Test all cause and effects: Yes				Confirm site is left tidy and all surplus materials removed: Yes		
	Confirm system is free of all faults and fully operational: Yes				Complete Log Book and inform responsible person of result of visit: Log book completed		
Notes	See report for recommendations						

Asset Register - Fire Alarm System Component

Asset ID	Location	Floor	Type	Zone		Make	Date Tested	Pass / Fail
15317	front entrance by panel		MCP	3			22/07/2025	Pass
Test Readings	Visual Inspection:				Functional Test:			
Notes								

Tamar Security Ltd is registered in England and Wales, Registration No. 05455843
VAT Registration No. 857 7423 87
Director: Martin Shearer



CERTIFICATE NO. NAC/G/1835

TAMAR SECURITY

DOMESTIC AND COMMERCIAL FIRE AND SECURITY SOLUTIONS

Ulysses Park, Exeter, Devon EX2 7PH

T: 01392 368830

E: admin@tamarsecurity.co.uk

www.tamarsecurity.co.uk

CUSTOMER JOB NO. 244905 - 47245 - Justin Chaplin Fire Alarm - Maintenance

Asset Register - Fire Alarm System Component							
Asset ID	Location	Floor	Type	Zone	Make	Date Tested	Pass / Fail
15318	front entrance		Smoke Detector	3		22/07/2025	Pass
Test Readings	Visual Inspection:			Functional Test:			
Notes							
15319	main entrance outside disabled toilet		Smoke Detector	3		22/07/2025	Pass
Test Readings	Visual Inspection:			Functional Test:			
Notes							
15320	toilet hallway		Smoke Detector	3		22/07/2025	Pass
Test Readings	Visual Inspection:			Functional Test:			
Notes							
15322	kitchen		Heat Rate of Rise Detector	3		22/07/2025	Pass
Test Readings	Visual Inspection:			Functional Test:			
Notes							
15323	kitchen fire exit		MCP	3		22/07/2025	Pass
Test Readings	Visual Inspection:			Functional Test:			
Notes							
15325	pine hall		MCP	2		22/07/2025	Pass
Test Readings	Visual Inspection:			Functional Test:			
Notes							
15326	pine stock room		Smoke Detector	2		22/07/2025	Pass
Test Readings	Visual Inspection:			Functional Test:			
Notes							
15327	pine stock room fire exit		MCP	2		22/07/2025	Pass
Test Readings	Visual Inspection:			Functional Test:			
Notes							
15329	Oak hall fire exit double doors		MCP	2		22/07/2025	Pass
Test Readings	Visual Inspection:			Functional Test:			

Tamar Security Ltd is registered in England and Wales, Registration No. 05455843
VAT Registration No. 857 7423 87
Director: Martin Shearer



CERTIFICATE NO. NAC/G/1835

TAMAR SECURITY

DOMESTIC AND COMMERCIAL FIRE AND SECURITY SOLUTIONS

Ulysses Park, Exeter, Devon EX2 7PH

T: 01392 368830

E: admin@tamarsecurity.co.uk

www.tamarsecurity.co.uk

CUSTOMER JOB NO. 244905 - 47245 - Justin Chaplin Fire Alarm - Maintenance

Notes							
15330	Oak hall fire exit single door		MCP	2		22/07/2025	Pass
Test Readings	Visual Inspection:				Functional Test:		
Notes							
15333	children centre office electric cupboard		Smoke Detector	3		22/07/2025	Pass
Test Readings	Visual Inspection:				Functional Test:		
Notes							
15334	children centre hallway by disabled toilets		Smoke Detector	3		22/07/2025	Pass
Test Readings	Visual Inspection:				Functional Test:		
Notes							
15335	children centre hallway by disabled toilets		Smoke Detector	3		22/07/2025	Pass
Test Readings	Visual Inspection:				Functional Test:		
Notes							
15340	hallway outside children centre office		Smoke Detector	3		22/07/2025	Pass
Test Readings	Visual Inspection:				Functional Test:		
Notes							
15342	hallway fire exit		MCP	3		22/07/2025	Pass
Test Readings	Visual Inspection:				Functional Test:		
Notes							

Work Completed Notes

Materials Used

Description	Location	Used

Tamar Security Ltd is registered in England and Wales, Registration No. 05455843
VAT Registration No. 857 7423 87
Director: Martin Shearer



CERTIFICATE NO. NAC/G/1835

TAMAR SECURITY

DOMESTIC AND COMMERCIAL FIRE AND SECURITY SOLUTIONS

Ulysses Park, Exeter, Devon EX2 7PH

T: 01392 368830

E: admin@tamarsecurity.co.uk

www.tamarsecurity.co.uk

CUSTOMER JOB NO. 244905 - 47245 - Justin Chaplin
Fire Alarm - Maintenance

The above works have been supplied and installed to my complete satisfaction.

Customer:

Bob Weeks

Print Name



Signature

The above works have been supplied and installed as per relevant United Kingdom Standards.

Technician:

Justin Chaplin

Print Name



Signature

Tamar Security Ltd is registered in England
and Wales, Registration No. 05455843
VAT Registration No. 857 7423 87
Director: Martin Shearer



CERTIFICATE NO. NAC/G/1835