



Lightning Protection Report Certificate

PASS



FAIL

Site Name & Address:

Stowford Community Centre
Chambers Cl
Sidmouth
EX10 9YL

Date of Inspection:

9th September 2026

Next inspection due:

9th August 2027

Testing Engineer:

DC

Contact:

Bob

Ground Conditions:

Dry

Readings:

	E1	E2	E3	E4	E5	E6										
Earth reading obtained	29.1	39.2	34.5	19.3	33.4	59.1										
Long test (if above is high)																
System Reading																

Earth reading obtained**Long test (if above is high)****Reading back through system****Required earth reading**

_____ 60 Ohms or under (No. of connected down conductors multiplied by ten)
_____ 10 Ohms or under (combined system reading)

Condition of external system including faults/defects (if any):

The lightning protection system appears to be in good working order throughout.

Does the external system conform to BS EN 62305:2011?

☒ Yes

☐ No

If not, why not?

Surge protection installed?

Not visible

M.E.T. equi-potentially bonded to the system?

Not visible

Air Termination Network:

Type of network

☐ Surface
☐ Capping

☒ Concealed
☐ Steel frame

☐ Metal roof utilised
☐ None present

Strike plates/finials used (under tile systems)

☒ Yes

☐ No

☐ N/A

Conductor material used

☐ Copper

☒ Aluminium

☐ Unknown (Possibly bare aluminium)

Colour of sheathing (if any)

☒ Bare
☐ Grey

☐ Brown
☐ Stone

☐ Black
☐ White

☐ N/A

Down conductor:

E1 E2 E3 E4 E5 E6

Aluminium (concealed)

☒
☒
☒
☒
☒
☒
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐

Copper

☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐

Steel frame/reinforcing

☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐

Rainwater pipe

☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐

Colour:

Bare

☒
☒
☒
☒
☒
☒
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐

Brown

☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐

Stone

☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐

Black

☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐

Grey

☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐

White

☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐

Painted

☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐

Test Clamp:

Bimetallic

☒
☒
☒
☒
☒
☒
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐

GM Square

☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐

Ali Square

☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐

"G" clamp

☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐

"B" bond

☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐

None

☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐

Anti-vandal guard:

Galvanised

☐
☐
☐
☐
☐
☐
☐
☐
☐
☐